

REPORTS ACCEPTED DURING JULY 2008 FOR FY 2007 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/GRP	MFR/DISTRIB	MY/MAKE/MODEL/STYLE	RESULT/HSNO
118	KAR 004	HONDA	2008 ACURA RDX MPV 4-DOOR	PASS 639816
118	KAR 005	SUZUKI	2008 SUZUKI SX4 4-DOOR SEDAN	PASS 639813
225	MGA 005	KIA	2006 KIA SORENTO MPV 4-DOOR	PASS 639827
225	MGA 003	TOYOTA	2007 TOYOTA YARIS 4-DOOR SEDAN	PASS 639828

REPORTS ACCEPTED DURING JULY 2008 FOR FY 2008 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/GRP	MFR/DISTRIB	MY/MAKE/MODEL/STYLE	RESULT/HSNO
105	TRC 001	GMC	2008 CHEVROLET EXPRESS VAN 3-DOOR	PASS 639807
118	GTL 002	HYUNDAI	2008 HYUNDAI SONATA 4-DOOR SEDAN	PASS 639806
118	GTL 003	FORD	2008 FORD EDGE MPV 4-DOOR	PASS 639805
206	KAR 002	TOYOTA	2008 TOYOTA HIGHLANDER DOOR LATCH/HINGE	PASS 639785
206	KAR 003	TOYOTA	2008 TOYOTA HIGHLANDER DOOR LATCH/HINGE	PASS 639808
206	KAR 004	TOYOTA	2008 SCION XB DOOR LATCH/HINGE	PASS 639784
206	KAR 005	TOYOTA	2008 SCION XB DOOR LATCH/HINGE	PASS 639809
206	KAR 006	TOYOTA	2008 TOYOTA SIENNA DOOR LATCH/HINGE	PASS 639810
206	KAR 007	TOYOTA	2008 TOYOTA SIENNA DOOR LATCH/HINGE	PASS 639812
206	KAR 008	TOYOTA	2008 TOYOTA SEQUOIA DOOR LATCH/HINGE	PASS 639811
206	MGA 002	CHRYSLER LLC	2008 CHRYSLER TOWN & COUNTRY DOOR LATCH/HINGE	PASS 639815
206	MGA 005	FORD	2008 FORD TAURUS X DOOR LATCH/HINGE	PASS 639814
206	MGA 014	HONDA	2008 HONDA FIT DOOR LATCH/HINGE	PASS 639826
209	DTB 013	MITSUBISHI	2008 MITSUBISHI LANCER SEAT BELT ASSY.	PASS 639820
209	DTB 014	NISSAN	2008 INFINITI EX35 SEAT BELT ASSY.	PASS 639821

REPORTS ACCEPTED DURING JULY 2008 FOR FY 2008 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HSNO
209	DTB 015	NISSAN	2008 NISSAN ROGUE SEAT BELT ASSY.	PASS 639822
209	UST 011	GMC	2009 CHEVROLET AVEO DRIVER SEAT BELT ASSY.	PASS 639817
209	UST 016	TOYOTA	2008 TOYOTA CAMRY SEAT BELT ASSY.	PASS 639819
209	UST 017	TOYOTA	2008 LEXUS ES350 FRONT RIGHT SEAT BELT ASSY.	PASS 639818
209	UST 018	TOYOTA	2008 TOYOTA RAV4 SEAT BELT ASSY.	PASS 639823
209	UST 019	TOYOTA	2008 SCION XB SEAT BELT ASSY.	PASS 639824

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L – LABELING

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH JULY 2008
(CI NUMBER SYSTEM EXAMPLE: "CI-208-061220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2007)**

NONE

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition

CT Compliance Test

IN Inspection

CP Complaint

ID Part 574

MI Mfgr. Inquiry

MD Mfgr. Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH JULY 2008
(PE NUMBER SYSTEM EXAMPLE: "PE-208-061220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2007)**

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-108-080515C	Zomkspeed/2008 Zomkspeed combination lamps/missing amber side reflex reflectors	MI
PE-108-080515D	Dream Team Motorsport/2008 Dream Team combination lamps/missing amber side reflex reflectors	MI
PE-108-080515E	Sprinter Power/2008 Sprinter Power combination lamps/missing amber side reflex reflectors	MI
PE-108-080515I	Spyder Inc./2008 Spyder Inc. combination lamps/ missing amber side reflex reflectors	MI
PE-108-080515J	Edixworks/2008 Edixworks combination lamps/missing amber side reflex reflectors	MI
PE-201-080722	General Motors/2008 Chevrolet HHR/Door assembly located in the center panel of vehicle tested did not remain closed	CT

PEs OPENED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-108-080515	Anw Group/2007 Eagle Eyes Dodge/Halogen headlamps-photometric test	CT
PE-108-080515	X3 Racing/Data Request	MI
PE-108-080716	Volkswagen of North America/2008 Volkswagen Golf/Data request	MI
PE-108-080516	Boken Corporation/Boken/Data request	MI
PE-108-080516	Allsman Enterprises/Allsman/Data request	MI
PE-108-080516	Sportiva Motors/Sportiva/Data request	MI

PEs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
 CT Compliance Test
 IN Inspection
 CP Complaint
 ID Part 574
 MI Mfgr. Inquiry
 MD Mfgr. Defect