From: Ansley, Alexander (NHTSA)

"CHRIS.LANGLOIS@ZEROMOTORCYCLES.COM"

Subject: *NHTSA Update: New Changes to Part 573 Recall Report Form*

Date: Wednesday, August 2, 2017 4:04:00 PM **Attachments:** image001.png

Attachments: image001.png image002.png

Good Afternoon, NHTSA Recalls Portal User:

NHTSA has recently introduced 2 new changes to the Part 573 Recall Report accessible through the online portal. Those changes are as follows:

1- To ensure compliance with the regulation (Part 573.6 (c)(2)), we ask that you include the basis for how the recall population was determined as well as how the recall products are different from similar products that were not included in the recall. We ask that you enter this information in the field shown below, in the "Add Product" area of the Part 573 Recall Report.



2- To comply with the Motor Vehicle Safety Act, 49 U.S.C. §30119(g) (Section 24116 of the FAST Act codified, found here), the name, description, and part number for the recalled component must be provided in the Part 573 Recall Repot. For recall reports your company submits to NHTSA, please provide that detail in the below field in the "Identify the Remedy" section:

cid:image003.jpg@01D30B75.389FEB00
_

Thank you & please let us know if you have any questions,

Recalls Portal Team
Office of Defects Investigation (ODI)
National Highway Traffic Safety Administration (NHTSA)
U.S. Department of Transportation (DOT)
https://map.safercar.gov/mportal/signin