

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: MARCH 15, 2004

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "**CI-208-020320**")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "**PE-214-020320**")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)	CP (Complaint)	MD (Manufacturer Defect)
ID (Part 574)	MI (Manufacturer Inquiry)	

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure
FAIL - I: inspection failure
FAIL - L: labeling or instruction failure

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
27	202	Head Restraints	Vehicle-15	TEST
28	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
29	204	Steering Control Rearward Displacement	Vehicle-17	TEST
30	205	Glazing Materials (Inspection)	Equipment	Insp.-6
31	206	Door Locks & Door Retention Components	Equip.-8	TEST
32	207	Seating Systems	Vehicle-18	TEST
33	208	Occupant Crash Protection	Vehicle-19	TEST
34	209	Seat Belt Assemblies	Equip.-9	TEST

35	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
36	212	Windshield Mounting	Vehicle-21	TEST
37	213	Child Restraint Systems	Equip.-10	TEST
38	214	Side Impact Protection	Vehicle-22	TEST
39	216	Roof Crush Resistance	Vehicle-23	TEST
40	217	Bus Window Retention & Release	Vehicle-24	TEST
41	218	Motorcycle Helmets	Equip.-11	TEST
42	219	Windshield Zone Intrusion	Vehicle-25	TEST
43	220	School Bus Rollover Protection	Vehicle-26	TEST
44	221	School Bus Body Joint Strength	Vehicle-27	TEST
45	222	School Bus Passenger Seating	Vehicle-28	TEST
46	223	Rear Impact Guards	Equip.-12	TEST
47	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
48	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
49	301	Fuel System Integrity	Vehicle-30	TEST
50	302	Flammability of Interior Materials	Equip.-13	TEST
51	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
52	304	CNG Fuel Container Integrity	Equip.-14	TEST
53	305	Electric Vehicles	Vehicle-32	TEST
54	401	Interior truck Release	Vehicle	TEST
55	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 34 vehicle standards, 14 equipment standards, 7 inspection standards				

REPORTS ACCEPTED DURING FEBRUARY 2004 FOR FY 2003 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HS NO.
225	GTL 002	GMC	2003 BUICK RENDEZVOUS MPV 4-DOOR	PASS 637005

REPORTS ACCEPTED DURING FEBRUARY 2004 FOR FY 2004 TEST PROGRAM

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HS NO.
206	KAR 002	FORD	2004 FORD FREESTAR DOOR LATCH/HINGE	PASS 637009
206	MGA 003	KIA	2004 KIA SORENTO DOOR LATCH/HINGE	PASS 637010
209	DTB 001	MERCEDES-BENZ	2004 MERCEDES ML350 SEAT BELT ASSY.	PASS 637007
209	DTB 002	MERCEDES-BENZ	2004 MERCEDES S430 SEAT BELT ASSY.	PASS 637008
209	DTB 003	HONDA	2004 HONDA ACURA SEAT BELT ASSY.	PASS 637019
209	DTB 004	HONDA	2004 HONDA ACURA SEAT BELT ASSY.	PASS 637020
209	DTB 005	HONDA	2004 HONDA INSIGHT SEAT BELT ASSY.	PASS 637021
213	UST 018	BRITAX	2004 BRITAX MARATHON CONV. CHILD RESTRAINT	PASS 637013
213	UST 019	BRITAX	2004 BRITAX WIZARD CONV. CHILD RESTRAINT	PASS 637014
213	UST 020	BRITAX	2004 BRITAX ROUNABOUT CONV. CHILD RESTRAINT	PASS 637015
213	UST 021	BRITAX	2004 BRITAX EXPRESSWAY CHILD RESTRAINT	PASS 637016
213	UST 022	BRITAX	2004 BRITAX HUSKY CHILD RESTRAINT	PASS 637017
213	UST 060	PEG PEREGO	2004 PEG PEREGO PRIMO VIAGGIO CHILD RESTRAINT	PASS 637018

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L - LABELING

TIRE REPORTS ACCEPTED FEBRUARY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	RESULT/ HSNO
109	SSS 001	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR EAGLE F1 M644TAWR1003	PASS 6276376
109	SSS 002	BRIDGESTONE HIKONE PLANT	2004 BRIDGESTONE TURANZA LS-H ELA6CJC5101	PASS 6276377
109	SSS 003	JIANGSU HANTA TIRE BIAS PLANT	2004 HERITAGE PERFORMANCE TR BJ9WD4E1603	PASS 6276378
109	SSS 005	MICHELIN NORTH AMERICA CANADA	2004 MICHELIN WEATHERWISE HNC7LKPV0803	PASS 6276379
109	SSS 006	FEDERAL CORP.	2004 FEDERAL FORMOZA FDI UXA61603	PASS 6276380
109	SSS 007	SOCIETA PER AZONI MICHELIN ITA	2004 MICHELIN AGILITY HDH3JCKX1002	PASS 6276381
109	SSS 008	KELLY-SPRINGFIELD TIRE CO.	2004 ULTRA TOUR LS PLM319LR1603	PASS 6276382
109	SSS 009	GOODYEAR TIRE & RUBBER CO.	2004 ROADHANDLER VOYAGER LX P205/70R15 95S	PASS 6276383
109	SSS 010	KELLY-SPRINGFIELD TIRE CO.	2004 LEE ALL WEATHER PLM3FRKR2903	PASS 6276384
109	SSS 011	CHENG SHIN RUBBER IND. CO. LTD.	2004 CHAPARRAL SUV HP UYGPABCW3402	PASS 6276385
109	SSS 013	KELLY-SPRINGFIELD TIRE CO.	2004 WILD COUNTRY RADIAL XTX PJ703TKR1103	PASS 6276387
109	SSS 014	BRIDGESTONE/ FIRESTONE N.A.	2004 PEERLESS PRESIDENT TOURING SE HYM3TPD2803	PASS 6276388
109	SSS 015	COOPER TIRE & RUBBER CO.	2004 COOPER DISCOVER AT T70C4X2303	PASS 6276389
109	SSS 016	BRIDGESTONE/ FIRESTONE N.A.	2004 GILLETE GOLDEN BEAR TOURING W2XOTPO2103	PASS 6276390
109	SSS 017	YOKOHAMA TIRE CORP.	2004 YOKOHAMA AVID T4 P225/60R16 97T	PASS 6276391
109	SSS 018	COOPER TIRE & RUBBER CO.	2004 MASTERCRAFT AVENGER LSR UPX3FM20703	PASS 6276392
109	SSS 019	MICHELIN NORTH AMERICA INC.	2004 MICHELIN DESTINY M33VF7LX2903	PASS 6276393
109	SSS 020	COOPER TIRE & RUBBER CO.	2004 DEAN TIRES STINGER RADIAL GTS 3DM2DK62903	PASS 6276394
109	SSS 021	BRIDGESTONE/ FIRESTONE CANADA	2004 FIRESTONE DESTINATION LE VNT6D101103	PASS 6276395
109	SSS 022	BRIDGESTONE/ FIRESTONE N.A.	2004 BRIDGESTONE EAGER OBUPPEI2203	PASS 6276396
109	SSS 023	HANKOOK TIRE MFG. CO. LTD.	2004 HANKOOK RADIAL H713 T7UNAHH1103	PASS 6276423
109	SSS 025	GOODYEAR DUNLOP TIRE N.A. LTD.	2004 DUNLOP GRANDTREK DBDAC13R2803	PASS 6276397
109	SSS 026	BRIDGESTONE/ FIRESTONE N.A.	BRIDGESTONE DUELER DLT 7XCUDLO3002	PASS 6276400

TIRE REPORTS ACCEPTED FEBRUARY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	RESULT/ HSNO
109	SSS 027	YOKOHAMA RUBBER CO.	2004 YOKOHAMA TYPE-1 S/T FBLJM4E1301	PASS 6276398
109	SSS 028	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR EAGLE GT II MKRHL22HR0803	PASS 6276401
109	SSS 029	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR EAGLE LS M62AHMDR2803	PASS 6276402
109	SSS 030	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR FORTERA HL EDITION PDCUMWHR3003	PASS 6276404
109	SSS 031	YOKOHAMA TIRE CORP.	2004 NATIONAL COMMANDO XT CC3FVM30103	PASS 6276405
109	SSS 032	COPPER TIRE & RUBBER CO.	2004 DOMINATOR SPORT A/T UT72XBR3203	PASS 6276406
109	SSS 033	COOPER TIRE & RUBBER CO.	2004 DOMINATOR SPORT G/T UTZUXD40903	PASS 6276422
109	SSS 034	BRIDGESTONE/ FIRESTONE N.A.	2004 BRIDGESTONE DUELER H/L 7XCUP1B2803	PASS 6276407
109	SSS 035	COOPER TIRE & RUBBER CO.	2004 COOPER DISCOVERER H/T UT7OC5U3003	PASS 6276408
109	SSS 036	UNIROYAL GOODRICH TIRE MFG.	2004 B.F. GOODRICH REVELATION TOURING BHM3BH213403	PASS 6276421
109	SSS 037	YOKOHAMA TIRE CORP.	2004 YOKOHAMA YK 4200 CCA68WN030	PASS 6276424
109	SSS 038	KUMHO & CO. INC.	2004 KUMHO TOURING PLUS 732 H2UDYP015102	PASS 6276409
109	SSS 039	GENERAL TIRE & RUBBER CO.	2004 GENERAL XP2000 A4 A3XC3B30802	PASS 6276410
109	SSS 040	YOKOHAMA RUBBER CO.	2004 YOKOHAMA GEOLANDER G039 FBLJNHT0203	PASS 6276411
109	SSS 041	GOODYEAR DUNLOP TIRE N.A. LTD.	2004 REMINGTON XT-120HR 400 DBXOE29R4502	PASS 6276335
109	SSS 042	GENERAL TIRE & RUBBER CO.	2004 GENERAL XP2000 II A3XO2NB0403	PASS 6276412
109	SSS 043	GOODYEAR DUNLOP TIRE N.A. LTD.	2004 DUNLOP RADIAL ROVER A/T DAO9GA2R3203	PASS 6276413
109	SSS 044	PIRELLI LTD.	2004 PIRELLI P400 TOURING XL9H99722303	PASS 6276414
109	SSS 045	BRIDGESTONE/ FIRESTONE N.A.	2004 PEERLESS FORCE 4 A/T W2CUW442903	PASS 6276415
109	SSS 046	BRIDGESTONE/ FIRESTONE N.A.	2004 DAYTON TIMBERLINE HT W2CUTD42903	PASS 6276416
109	SSS 048	MICHELIN NORTH AMERICA INC.	2004 MICHELIN LTX M/S B7JCDC7X2703	PASS 6276417
109	SSS 049	KELLY-SPRINGFIELD TIRE CO.	2004 KELLY-SPRINGFIELD MULTI-MILE WILDCAT PJ7OPMLLR2002	PASS 6276418
109	SSS 050	FEDERAL CORP.	2004 FEDERAL SUPER STEEL 635 UXA61603	PASS 6276419

TIRE REPORTS ACCEPTED FEBRUARY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	RESULT/ HSNO
109	SSS 051	BRIDGESTONE/ FIRESTONE N.A.	2004 DAYTON TIMBERLINE A/T W2CUTDD2803	PASS 6276336
109	SSS 052	YOKOHAMA RUBBER CO.	2004 YOKOHAMA GEOLANDAR A/T FBLJNMU2003	PASS 6276337
109	SSS 053	GOODYEAR DUNLOP TIRE N.A. LTD.	2004 REMINGTON WIDE BRUTE A/W DAT6F881502	PASS 6276338
109	SSS 054	BRIDGESTONE HIKONE PLANT	2004 PEERLESS PRESIDENT II HYM3DX2803	PASS 6276339
109	SSS 055	BRIDGESTONE HIKOLE PLANT	2004 BRIDGESTONE POTENZA RE92 EL9PCDE4602	PASS 6276340
109	SSS 056	COPPER TIRE & RUBBER CO.	2004 DOMINATOR TOURING II U9MITUD2803	PASS 6276341
109	SSS 057	PIRELLI S.A.	2004 PIRELLI CINTURATO P3000 XLXOB1084302	PASS 6276342
109	SSS 058	HANKOOK TIRE (JIAXING) CO. LTD.	2004 HANKOOK P215/70R15 97S 1GUNAPH506	PASS 6276343
109	SSS 059	BRIDGESTONE/ FIRESTONE N.A.	2004 PEERLESS AMBASSADOR HYULAP11703	PASS 6276344
109	SSS 060	COOPER TIRE & RUBBER CO.	2004 DEAN TIRES WILD CAT TOURING UTUYDMU3103	PASS 6276345
109	SSS 061	KELLY-SPRINGFIELD TIRE CO.	2004 LEE STEEL TRAK PREMIUM PJM33RLR3003	PASS 6276346
109	SSS 062	MICHELIN NORTH AMERICA INC.	2004 MICHELIN PILOT XGT H4 3R3VC44YX1503	PASS 6276347
109	SSS 063	KELLY-SPRINGFIELD TIRE CO.	2004 PATHFINDER LUXURY SUV PJ724FKR2303	PASS 6276348
109	SSS 064	COOPER TIRE & RUBBER CO.	2004 MASTERCRAFT COURSER AWT UTCUFLF5002	PASS 6276349
109	SSS 065	KELLY-SPRINGFIELD TIRE CO.	2004 ULTRA TOUR SPORT SUV PJ7OYFL3403	PASS 6276350
109	SSS 066	KELLY-SPRINGFIELD TIRE CO.	2004 REMINGTON EMERALD LX PJXO3CK2002	PASS 6276420
109	SSS 067	BRIDGESTONE/ FIRESTONE CANADA INC.	2004 BRIDGESTONE DUELER A/T D693 PBT6P683103	PASS 6276351
109	SSS 068	UNIROYAL GOODRICH TIRE MFG.	2004 SPORT KING STEEL RADIAL AT BF70B4JJ0603	PASS 6276352
109	SSS 069	COOPER TIRE & RUBBER CO.	2004 MASTERCRAFT COURSER A/T UTCUFLF5002	PASS 6276353
109	SSS 070	KELLY-SPRINGFIELD TIRE CO.	2004 GOODYEAR WRANGLER RT/S PJCUC6HR3203	PASS 6276354
109	SSS 071	BRIDGESTONE/ FIRESTONE N.A.	2004 BRIDGESTONE DUELER A/T 7X72P1B30034	PASS 6276356
109	SSS 072	MICHELIN NORTH AMERICA INC.	2004 MICHELIN ENERGY MXV4 PLUS M33VEXMX1403	PASS 6276357
109	SSS 073	COOPER TIRE RUBBER CO.	2004 MASTERCRAFT COURSER HTR UTCUMA1803	PASS 6276358

TIRE REPORTS ACCEPTED FEBRUARY 2004 FOR FY 2004 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/BRAND/ TIRE_NAME/ID_NUMBER	RESULT/ HSNO
109	SSS 074	BRIDGESTONE HIKONE PLANT	2004 BRIDGESTONE DUELER A/T REVO EL7ODDJ2703	PASS 6276359
109	SSS 075	BRIDGESTONE HIKONE PLANT	2004 BRIDGESTONE POTENZA RE910 ELA6CNJ1903	PASS 6276360
109	SSS 076	GOODYEAR TIRE & RUBBER CO.	2004 GOODYEAR WRANGLER HP M6YNFOER2903	PASS 6276361
109	SSS 077	KELLY-SPRINGFIELD TIRE CO.	2004 SUMMIT CASCADE LUXURY SUV PJ724NLR2103	PASS 6276362
109	SSS 078	MICHELIN NORTH AMERICA INC.	2004 MICHELIN ENERGY MXV4 PLUS B63V704X202	PASS 6276363
109	SSS 079	BRIDGESTONE/ FIRESTONE N.A.	2004 BRIDGESTONE DUELER APT A/T Y7HLPUN0203	PASS 6276364
109	SSS 080	KELLY-SPRINGFIELD TIRE CO.	2004 MULTI-MILE WILD COUNTRY TOURING PJ7034KR4102	PASS 6276365
109	SSS 081	TOYO RUBBER IND. CO. LTD.	2004 TOYO OPEN COUNTRY CX3F9PD1503	PASS 6276366
109	SSS 082	BRIDGESTONE/ FIRESTONE N.A.	2004 WIDETRACK BAJA H/T W272WHC2203	PASS 6276367
109	SSS 083	GOODYEAR CANADA INC.	2004 GOODYEAR WRANGLER AT/S 4BT6FDDR2803	PASS 6276368
109	SSS 084	GENERAL TIRE & RUBBER CO.	2004 GENERAL AMERITRAC A3CU45FW2903	PASS 6276369
109	SSS 085	KUMHO & CO. INC.	2004 KUMHO ECSTA STX H2WHYC3A1802	PASS 6276370
109	SSS 086	UNIROYAL GOODRICH TIRE MFG.	2004 UNIROYAL LAREDO ALL SEASON AW BF70B4UU2703	PASS 6276371
109	SSS 087	BRIDGESTONE/ FIRESTONE N.A.	2004 WIDETRACK RADIAL H/R W2XOD1C2503	PASS 6276372
109	SSS 088	SICUP S.N.C. USINEUNIROYAL	2004 CONTINENTAL CONTI TOURING CONTAC LLVNPXB2503	PASS 6276373
109	SSS 089	KELLY-SPRINGFIELD TIRE CO.	2004 MONARCH TIRES ROAD HUGGER RADIAL G PJM1DXKR1503	PASS 6276374
109	SSS 090	KELLY-SPRINGFIELD TIRE CO.	2004 LEE TIRES RIDGE RUNNER RADIAL PJ7012LR2603	PASS 6276375

Note: The tire description usually includes an ID number. The tire ID number changes by production week and it is not a tire serial number. Tire ID numbers that are identical indicate that the tires were manufactured during the same week, not that they are the same tire.

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH FEBRUARY 2004
(CI NUMBER SYSTEM EXAMPLE: "CI-208-031220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2003)**

CI NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
CI-108-010831	Astex USA/HID conversion/Headlamp/Electrical dimensional marking req.	MI
CI-108-031205B	Santeca Electronics/2003 Thunder Beam HID conversion/Replaceable light source and ballasts may not comply with S7.7	MI
CI-218-030708	Wombat Trading Co./2003 M2R Motorcycle helmet/Impact at ambient	CT
CI-218-030303	HJC/2002 Z1RZFR-1/Penetration at ambient at high temperature	CT
CI-218-030805	Strategic Sports BVI Ltd./2003 Zamp-S1/Penetration at ambient at low temperature	CT
CI-108-040101F	Global Premier LLC/HID Conversion/Replaceable light sources and ballasts may not comply with S7.7	MI

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

CI NO.	MFR/MY/MAKE/MODEL/FAILURE
CI-108-031205C	McCulloch Motors/2003 McCulloch HID conversion/Replaceable light source and ballasts may not comply with S7.7/Closed by NHTSA 2/9/2004
CI-108-040101A	JF Manufacturing/Eagle Eye HID Conversion/Replaceable light sources and ballasts may not comply with S7.7/Manufacturer's noncompliance on 2/10/2004
CI-108-040101B	Streetglow Inc./HID Conversion/Replaceable light sources and ballasts may not comply with S7.7/ Manufacturer's noncompliance on 2/25/2004
CI-108-040101C	Outback Products/HID Conversion/Replaceable light sources and ballasts may not comply with S7.7/Closed by NHTSA 2/25/2004
CI-108-040101D	GR Motorsport Inc./HID Conversion/Replaceable light sources and ballasts may not comply with S7.7/ Manufacturer's noncompliance on 2/27/2004
CI-108-040101E	NU Performance Distributing/HID Conversion/Replaceable light sources and ballasts may not comply with S7.7/Manufacturer's noncompliance on 2/25/2004
CI-218-030909	Shokan International Co., Ltd./2003 AFX FX-9/ Impact at ambient/Closed by NHTSA 2/2/2004

CAUSE:

CT Compliance Test
 IN Inspection
 CP Complaint
 ID Part 574
 MI Manufacturer Inquiry
 MD Manufacturer Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH FEBRUARY 2004
(PE NUMBER SYSTEM EXAMPLE: "PE-208-031220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2003)**

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-108-030602	United Marine Inc./2003 Trailer lamp assembly/Complaint relative to photometry	MI
PE-120-021227	Blue Bird Body Co./2002 School Bus/Tire inflation pressure	CT
PE-121-021104	White's/Keene Manufacturing/2002 Trailer/Updated from OA/Function at ABS device	MI
PE-208-030501	Toyota/2003 Toyota Tacoma/Sled test-neck compression > 4000	IN
PE-116-040115	Star Brite Inc./2004 Star Brite/Hvy duty brake fluid/High temperature stability	CT
PE-217-030801	Atwood Mobile Products/Emergency exit window/Push out window/Window retention	MI
PE-217-030819	Liberty Bus Inc./2003 Liberty Freedom/School bus/Positive door opening device < 90 degrees	CT
PE-221-030828	Amtran Corp./2003 Amtran IC3S5/Joint tensile strength less than 60%	CT
PE-222-030815	Liberty Bus Inc./2003 Liberty Freedom/Schoolbus/Passenger seat pulled out of floor	CT
PE-304-030905	Structural Composites Ind./2003 StructuralComposites/CNG fuel container ruptured during bonfire test	CT
PE-VAR-031120	Legendary Motorcars and Coachworks/2003 Lincoln Navigator/Various test failures (108, 111, 120, 205 and 217)	IN

PEs OPENED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-225-031128	Accubuilt/2003 Accubuilt Bus under 10K GVWR/Not enough tether anchorages	IN

PEs CLOSED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-123-010730	Currie Technologies, Inc./1999 Currie/Electric Bicycle/No engine stop or hand throttle control/Closed by NHTSA 2/27/2004
PE-213-030812	Evenflo Co/2003 Evenflo Vanguard/Head excursion measured 32.5 in; req 32 in./Closed by NHTSA 2/27/2004
PE-218-030610	Davida UK Limited/2003 Davida motorcycle helmet/Labeling/Closed by NHTSA 2/26/2004
PE-218-030709	Hong Jin Crown Corp./2002 Icon Alliance/Retention system at ambient/Closed by NHTSA 1/30/2004
PE-221-030827	Mid Bus Inc./2003 Mid Bus/Joint tensile strength less than 60%/ Manufacturer's noncompliance on 12/28/2003
PE-222-030609	Mid Bus Inc./2003 Mid bus/Seat back height and surface area/ Manufacturer's noncompliance on 12/31/2003
PE-225-031202	Starcraft Automotive Group/2003 Starcraft Bus under 10K GVWR/Not enough tether anchorages/ Manufacturer's noncompliance on 12/04/2003
PE-225-031128	Accubuilt/2003 Accubuilt Bus under 10K GVWR/Not enough tether anchorages/ Manufacturer's noncompliance on 12/12/2003
PE-301S-030513	US Bus Corp./2003 US Bus/GM chassis sturdibus/Upgraded from OA, insufficient certification data/Closed by NHTSA 2/20/2004
PE-575-031021	Hankook Tire/2003 Hankook mileage plus GT/Traction rating/Closed by NHTSA 2/1/2004
PE-575-030623	Goodyear Tire & Rubber Co./2002 Goodyear Aquatred 3/Traction rating/Closed by NHTSA 2/19/2004

CAUSE:

CT Compliance Test

IN Inspection

CP Complaint

ID Part 574

MI Manufacturer Inquiry

MD Manufacturer Defect