

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: JULY 2005

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "**CI-208-020320**")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "**PE-214-020320**")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)

CP (Complaint)

MD (Manufacturer Defect)

ID (Part 574)

MI (Manufacturer Inquiry)

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
27	202	Head Restraints	Vehicle-15	TEST
28	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
29	204	Steering Control Rearward Displacement	Vehicle-17	TEST
30	205	Glazing Materials (Inspection)	Equipment	Insp.-6
31	206	Door Locks & Door Retention Components	Equip.-8	TEST
32	207	Seating Systems	Vehicle-18	TEST
33	208	Occupant Crash Protection	Vehicle-19	TEST
34	209	Seat Belt Assemblies	Equip.-9	TEST

35	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
36	212	Windshield Mounting	Vehicle-21	TEST
37	213	Child Restraint Systems	Equip.-10	TEST
38	214	Side Impact Protection	Vehicle-22	TEST
39	216	Roof Crush Resistance	Vehicle-23	TEST
40	217	Bus Window Retention & Release	Vehicle-24	TEST
41	218	Motorcycle Helmets	Equip.-11	TEST
42	219	Windshield Zone Intrusion	Vehicle-25	TEST
43	220	School Bus Rollover Protection	Vehicle-26	TEST
44	221	School Bus Body Joint Strength	Vehicle-27	TEST
45	222	School Bus Passenger Seating	Vehicle-28	TEST
46	223	Rear Impact Guards	Equip.-12	TEST
47	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
48	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
49	301	Fuel System Integrity	Vehicle-30	TEST
50	302	Flammability of Interior Materials	Equip.-13	TEST
51	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
52	304	CNG Fuel Container Integrity	Equip.-14	TEST
53	305	Electric Vehicles	Vehicle-32	TEST
54	401	Interior truck Release	Vehicle	TEST
55	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 34 vehicle standards, 14 equipment standards, 7 inspection standards				

REPORTS ACCEPTED DURING JUNE 2005 FOR FY2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/GRP	MFR/DISTRIB	MY/MAKE/MODE/STYLE	RESULT/HSNO
105	TRC 001	BLUE BIRD	2005 BLUE BIRD VISION SCHOOL BUS	FAIL-L ¹ 637875
135	TRC 005	FORD	2004 LINCOLN LS 4-DOOR SEDAN	PASS 637848
135	TRC 006	VOLVO	2005 VOLVO S40 4-DOOR SEDAN	PASS 637850
206	KAR 007	DAIMLER/ CHRYSLER	2005 DODGE DAKOTA QUAD-CAB DOOR LATCH/HINGE	PASS 637849
206	KAR 008	GMC	2005 CHEVROLET EQUINOX DOOR LATCH/HINGE	PASS 637853
206	KAR 009	GMC	2005 CHEVROLET EQUINOX DOOR LATCH/HINGE	PASS 637854
206	MGA 017	TOYOTA	2005 TOYOTA SEQUOIA DOOR LATCH/HINGE	PASS 637886
206	MGA 018	TOYOTA	2005 TOYOTA SIENNA DOOR LATCH/HINGE	PASS 637897
208	MGA 001	FORD	2005 FORD FOCUS 4-DOOR SEDAN	PASS 637852
208	MGA 002	SUBARU	2005 SUBARU OUTBACK 4-DOOR WAGON	FAIL-L ² 637874
208	MGA 003	TOYOTA	2005 TOYOTA COROLLA 4-DOOR SEDAN	FAIL-P ³ 637871
208	MGA 004	DAIMLER/ CHRYSLER	2005 DODGE MAGNUM 4-DOOR WAGON	PASS 637876
208	MGA 005	TOYOTA	2005 TOYOTA HIGHLANDER MPV 4-DOOR	PASS 637863
209	DTB 010	PORSCHE	2005 PORSCHE CAYENNE SEAT BELT ASSY.	PASS 637851
209	DTB 017	VOLKSWAGEN	2005 VOLKSWAGEN PHAETON SEAT BELT ASSY.	PASS 637885
209	UST 001	VOLKSWAGON	2005 AUDI A6 SEAT BELT ASSY.	PASS 637855
212	MGA 001	FORD	2005 FORD FOCUS 4-DOOR SEDAN	PASS 637852
212	MGA 002	SUBARU	2005 SUBARU OUTBACK 4-DOOR WAGON	PASS 637874
212	MGA 003	TOYOTA	2005 TOYOTA COROLLA 4-DOOR SEDAN	PASS 637871
212	MGA 004	DAIMLER/ CHRYSLER	2005 DODGE MAGNUM 4-DOOR WAGON	PASS 637876
212	MGA 005	TOYOTA	2005 TOYOTA HIGHLANDER MPV 4-DOOR	PASS 637863

¹ Labeling-ABS warning lamp

² Same as footnote number 1

³ Passenager neck criteria (NIJ)

REPORTS ACCEPTED DURING JUNE 2005 FOR FY2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODE/STYLE	RESULT/ HSNO
213	UST 021	DOREL JUVENILE	2005 SAFETY 1ST ENSPIRA OHS CONV. CHILD RESTRAINT	PASS 637887
213	UST 050	TRIPLE PLAY PRO	2005 TRIPLE PLAY PRO SIT-N-STROLL CONV. CHILD RESTRAINT	FAIL-P ⁴ 637898
213	UST 051	PEG PEREGO	2005 PEG PEREGO PRIMO VIAGGIO INFANT CHILD RESTRAINT	PASS 637899
213	UST 052	BABY TREND	2005 BABY TREND LATCH LOC INFANT CHILD RESTRAINT	PASS 637900
213	UST 010	DOREL JUVENILE	2005 SAFETY 1 ST DESIGNER 22 LX INFANT CHILD RESTRAINT	PASS 637861
213	UST 011	DOREL JUVENILE	2005 COSCO ARRIVA W/BASE INFANT CHILD RESTRAINT	PASS 637862
213	UST 012	DOREL JUVENILE	2005 COSCO ARRIVA INFANT CHILD RESTRAINT	PASS 637864
213	UST 014	DOREL JUVENILE	2005 COSCO TLC INFANT CHILD RESTRAINT	PASS 637865
213	UST 015	DOREL JUVENILE	2005 COSCO TORIVA 5 POINT CONV. CHILD RESTRAINT	PASS 637866
213	UST 016	DOREL JUVENILE	2005 COSCO TORIVA O/H SHIE CONV. CHILD RESTRAINT	PASS 637867
213	UST 017	DOREL JUVENILE	2005 COSCO REGAL RIDE O/H CONV. CHILD RESTRAINT	PASS 637868
213	UST 018	DOREL JUVENILE	2005 SAFETY 1 ST COMFORT RIDE CONV. CHILD RESTRAINT	PASS 637869
213	UST 019	DOREL JUVENILE	2005 SAFETY 1 ST ENSPIRA 5 POINT CONV. CHILD RESTRAINT	PASS 637870
213	UST 020	DOREL JUVENILE	2005 SAFETY 1 ST INTERA CONV. CHILD RESTRAINT	PASS 637872
213	UST 022	DOREL JUVENILE	2005 COSCO ALPHA OMEGA 5-P COMB. CHILD RESTRAINT	PASS 637890
213	UST 023	DOREL JUVENILE	2005 EDDIE BAUER 3 IN 1 COMBINATION CHILD RESTRAINT	PASS 637891
213	UST 024	DOREL JUVENILE	2005 COSCO ALPHA OMEGA OHS COMB.CHILD RESTRAINT	PASS 637892
213	UST 025	DOREL JUVENILE	2005 COSCO SUMMIT DX BOOSTER CHILD RESTRAINT	PASS 637893
213	UST 026	DOREL JUVENILE	2005 COSCO VENTURA DX BOOSTER CHILD RESTRAINT	PASS 637894
213	UST 027	DOREL JUVENILE	2005 EDDIE BAUER HIGH BACK BOOSTER CHILD RESTRAINT	PASS 637895
213	UST 028	DOREL JUVENILE	2005 SAFETY 1ST VANTAGE POINT BOOSTER CHILD RESTRAINT	PASS 637896
213	UST 035	EVENFLO	2005 EVENFLO TRIBUTE 5 CONV. CHILD RESTRAINT	PASS 637838

⁴ Foam energy absorption failure

REPORTS ACCEPTED DURING JUNE 2005 FOR FY2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODE/STYLE	RESULT/ HSNO
213	UST 036	EVENFLO	2005 EVENFLO EXPRESS COMB. CHILD RESTRAINT	PASS 637839
213	UST 037	EVENFLO	2005 EVENFLO CHASE COMB. CHILD RESTRAINT	PASS 637840
213	UST 038	EVENFLO	2005 EVENFLO VISION COMBINATION CHILD RESTRAINT	PASS 637841
213	UST 039	EVENFLO	2005 EVENFLO DISCOVERY INFANT CHILD RESTRAINT	PASS 637842
213	UST 040	EVENFLO	2005 EVENFLO PORTABOUT 3 INFANT CHILD RESTRAINT	PASS 637843
213	UST 041	EVENFLO	2005 EVENFLO PORTABOUT 5 PRE INFANT CHILD RESTRAINT	PASS 637844
213	UST 042	EVENFLO	2005 EVENFLO TOT TAXI INFANT CHILD RESTRAINT	PASS 637845
213	UST 043	GRACO	2005 GRACO ASSURA INFANT CHILD RESTRAINT	PASS 637846
213	UST 044	GRACO	2005 GRACO SNUGRIDE 3 POINT INFANT CHILD RESTRAINT	PASS 637847
213	UST 045	GRACO	2005 GRACO SNUGRIDE 5 POINT INFANT CHILD RESTRAINT	PASS 637856
213	UST 046	GRACO	2005 GRACO COMFORT SPORT 5 CONV. CHILD RESTRAINT	PASS 637857
213	UST 047	GRACO	2005 GRACO COMFORT SPORT CONV. CHILD RESTRAINT	PASS 637858
213	UST 048	GRACO	2005 GRACO ULTRA CARGO BOOSTER CHILD RESTRAINT	PASS 637859
213	UST 049	GRACO	2005 GRACO TREASURED CARGO BOOSTER CHILD RESTRAINT	PASS 637860
214	VER 006	TOYOTA	2005 TOYOTA AVALON 4-DOOR SEDAN	PASS 637873
217	MGA 001	CORBEIL	2004 CORBEIL 30 PASSENGER SCHOOL BUS	PASS 637877
217	MGA 003	COLLINS	2004 COLLINS SUPER BANTAM SCHOOL BUS	PASS 637883
217	MGA 004	GIRARDIN	2005 GIRARDIN MBII SCHOOL BUS	PASS 637884
218	UST 006	NEXL SPORTS	2005 NEXL 05 PARTIAL MOTORCYCLE HELMET	FAIL-P ⁵ 637880
218	UST 007	NEXL SPORTS	2005 NEXL 05 PARTIAL MOTORCYCLE HELMET	FAIL-P ⁶ 637879
218	UST 008	SCORPION SPORTS	2005 SCORPION EXO-700 COMP. MOTORCYCLE HELMET	FAIL-P ⁷ 637878

⁵ Penetration failures: first strike; crown area

⁶ Penetration failure: second strike; crown area

⁷ Impact, rear location, flat anvil

REPORTS ACCEPTED DURING JUNE 2005 FOR FY2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODE/STYLE	RESULT/ HSNO
218	UST 009	BELL SPORTS	2005 BELL SPRINT COMP. MOTORCYCLE HELMET	PASS 637881
218	UST 010	KBC	2005 ONE HELMETS TROOPER COMP. FACIAL MOTORCYCLE HELMET	PASS 637901
218	UST 011	WOMBAT TRADING	2005 M2R 504 PARTIAL MOTORCYCLE HELMET	PASS 637902
301	MGA 001	FORD	2005 FORD FOCUS 4-DOOR SEDAN	PASS 637852
301	MGA 002	SUBARU	2005 SUBARU OUTBACK 4-DOOR WAGON	PASS 637874
301	MGA 003	TOYOTA	2005 TOYOTA COROLLA 4-DOOR SEDAN	PASS 637871
301	MGA 004	DAIMLER/ CHRYSLER	2005 DODGE MAGNUM 4-DOOR WAGON	PASS 637876
301	MGA 005	TOYOTA	2005 TOYOTA HIGHLANDER MPV 4-DOOR	PASS 637863
304	ATI 003	PRESSED STEEL	2005 PRESSED STEEL CNG FUEL CONTAINER TYPE 2, 3699 PSI	PASS 637888
304	ATI 004	PRESSED STEEL	2005 PRESSED STEEL CNG FUEL CONTAINER TYPE 2, 3600 PSI	PASS 637889

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L - LABELING

TIRE REPORTS ACCEPTED DURING JUNE 2005 FOR FY 2005 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/GRP	MFG/DISTRIB.	MY/BRAND/TIRE_NAME/ID_NUMBER	HSNO/RESULT
575	UTG 041	YOKOHAMA TIRE CORP.	2005 YOKOHAMA GEOLANDER H/T-S CC6R8XK2504	PASS 6276987
575	UTG 042	YOKOHAMA TIRE CORP.	2005 YOKOHAMA GEOLANDER H/T-S 6R8XK2504	PASS 6276988
575	UTG 045	GENERAL TIRE & RUBBER CO.	2005 GENERAL EXCLAIM A3XV3LY2604	PASS 6276989
575	UTG 046	GENERAL TIRE & RUBBER CO.	2005 GENERAL EXCLAIM A3XV3LY2604	PASS 6276990
575	UTG 049	BRIDGESTONE/ FIRESTONE CANADA	2005 FIRESTONE DESTINATION A/T VN73DA21704	PASS 6276991
575	UTG 050	BRIDGESTONE/ FIRESTONE CANADA	2005 FIRESTONE P265/75R16 VN73DA21704	PASS 6276992
575	UTG 053	NEXAN TIRE CORP.	2005 WOOSUNG SB-802 8ETBMD1404	PASS 6276993
575	UTG 054	NEXAN TIRE CORP.	2005 WOOSUNG SB-802 8ETBMD1404	PASS 6276994
575	UTG 057	OHTSU TIRE & RUBBER CO.	2005 FALKEN AZENIS ST115 V40LP20R1504	PASS 6276995
575	UTG 058	OHTSU TIRE & RUBBER CO.	2005 FALKEN AZENIS ST115 V40LP20R1504	PASS 6276996
575	UTG 061	BRIDGESTONE HOFU	2005 BRIDGESTONE TURANZA LS-H H49LCEE1202	PASS 6276997
575	UTG 062	BRIDGESTONE HOFU	2005 BRIDGESTONE TURANZA LS-H H49LCEE5103	PASS 6276998
575	UTG 066	NEXEN TIRE CORP.	2005 NEXEN ROADIAN-AT 8EWJJC0304	PASS 6277000
575	UTG 069	PIRELLI LTD.	2005 PIRELLI SCORPION STR XNA1D9454803	PASS 6277001
575	UTG 070	PIRELLI LTD.	2005 PIRELLI SCORPION STR XNA1D9454803	PASS 6277002
575	UTG 073	CHEN SHIN-TOYO TIRE & RUBBER CO.	2005 MAXXIS 750 BRAVO H/T 2UH0BBC5103	PASS 6277003
575	UTG 074	CHEN SHIN-TOYO TIRE & RUUBER CO.	2005 MAXXIS 750 BRAVO H/T 2UH0BBC5003	PASS 6277004
575	UTG 077	KUMHO & CO. INC.	2005 KUMHO ECSTA KH11 YOPWYA72004	PASS 6277005

Note: The tire description usually includes an ID number. The tire ID number changes by production week and it is not a tire serial number. Tire ID numbers that are identical indicate that the tires were manufactured during the same week, not that they are the same tire.

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH JUNE 2005
(CI NUMBER SYSTEM EXAMPLE: "CI-208-041220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2004)**

CI NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
CI-218-040430	Nexl Sports Products/2004 Nxl 05/Penetration at ambient at high temperature	CT

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

CI NO.	MFR/MY/MAKE/MODEL/FAILURE
CI-218-040923	Nexl Sports Products/2004 Nxl 101/Retention System at ambient after Immersion/Closed by NHTSA 5/25/05

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH JUNE 2005
(PE NUMBER SYSTEM EXAMPLE: "PE-208-041220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2004)**

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-121-041101	Indiana Phoenix Inc./2004 Air Brakes/Data request	MI
PE-222-050222	Les Entreprises Michel Corbeil/2004 Corbeil 30 passenger bus/Seat back height and surface area.	CT

PEs OPENED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-201-041110	Ford Motor Co./2005 Ford Escape/A-Pillar Hic > 1000	CT
PE-201-050228	Mazda North American Operations/2004 Mazda 6/Interior compartment door test	CT
PE-201-050325	General Motors Corp./2005 Buick Lactosse/Upper roof rail target (Ur2):1164 HIC<1000 HIC	CT
PE-217-050601	US Bus Corporation/2005 US Bus Sturdibus/ Window retention	CT
PE-222-050525	Blue Bird/2005 Blue Bird Vision/Barrier position and rear surface area	CT
PE-222-050530	US Bus Manufacturing/2005 US Bus Sturdibus/Seat and barrier performance forward	CT

PEs CLOSED SINCE LAST REPORT

PE NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-217-050601	US Bus Corporation/2005 US Bus Sturdibus/ Window retention/Manufacturer's noncompliance report 6/6/2005

CAUSE:

PE Petition
 CT Compliance Test
 IN Inspection
 CP Complaint
 ID Part 574
 MI Mfgr. Inquiry
 MD Mfgr. Defect