

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: JULY 2006

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "CI-208-020320")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "PE-214-020320")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)	CP (Complaint)	MD (Manufacturer Defect)
ID (Part 574)	MI (Manufacturer Inquiry)	

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R - Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equipment	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
24	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
25	135	Passenger Car Brake Systems	Vehicle-13	TEST
26	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
27	202	Head Restraints	Vehicle-15	TEST
28	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
29	204	Steering Control Rearward Displacement	Vehicle-17	TEST
30	205	Glazing Materials (Inspection)	Equipment	Insp.-6
31	206	Door Locks & Door Retention Components	Equip.-8	TEST
32	207	Seating Systems	Vehicle-18	TEST

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
33	208	Occupant Crash Protection	Vehicle-19	TEST
34	209	Seat Belt Assemblies	Equip.-9	TEST
35	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
36	212	Windshield Mounting	Vehicle-21	TEST
37	213	Child Restraint Systems	Equip.-10	TEST
38	214	Side Impact Protection	Vehicle-22	TEST
39	216	Roof Crush Resistance	Vehicle-23	TEST
40	217	Bus Window Retention & Release	Vehicle-24	TEST
41	218	Motorcycle Helmets	Equip.-11	TEST
42	219	Windshield Zone Intrusion	Vehicle-25	TEST
43	220	School Bus Rollover Protection	Vehicle-26	TEST
44	221	School Bus Body Joint Strength	Vehicle-27	TEST
45	222	School Bus Passenger Seating	Vehicle-28	TEST
46	223	Rear Impact Guards	Equip.-12	TEST
47	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
48	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
49	301	Fuel System Integrity	Vehicle-30	TEST
50	302	Flammability of Interior Materials	Equip.-13	TEST
51	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
52	304	CNG Fuel Container Integrity	Equip.-14	TEST
53	305	Electric Vehicles	Vehicle-32	TEST
54	401	Interior truck Release	Vehicle	TEST
55	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 34 vehicle standards, 14 equipment standards, 7 inspection standards				

REPORTS ACCEPTED DURING JUNE 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HS NO.
103	GTL 001	HYUNDAI	2006 HYUNDAI SONATA 4-DOOR SEDAN	PASS 638390
103	GTL 002	FORD	2006 FORD MUSTANG 2-DOOR COUPE	PASS 638391
103	GTL 003	FORD	2006 FORD FUSION 4-DOOR SEDAN	PASS 638392
103	GTL 004	MITSUBISHI	2006 MITSUBISHI ECLIPSE 2-DOOR COUPE	PASS 638393
104	GTL 001	HYUNDAI	2006 HYUNDAI SONATA 4-DOOR SEDAN	PASS 638395
104	GTL 002	FORD	2006 FORD FUSION 4-DOOR SEDAN	PASS 638396
104	GTL 003	FORD	2006 FORD MUSTANG 2-DOOR COUPE	PASS 638397
104	GTL 004	MITSUBISHI	2006 MITSUBISHI ECLIPSE 2-DOOR COUPE	PASS 638398
108	CAN 001	FORD	2003 VISTEON FORD F150 LAMPS	FAIL-P ¹ 638337
108	ITS 001	WAGNER	2002 CANDLEPOWER HALOGEN HB5 LAMPS	PASS 638339
108	ITS 002	WAGNER	2002 WAGNER HALOGEN HB5 LAMPS	PASS 638340
108	ITS 003	WAGNER	2005 VALUCRAFT HALOGEN HB5 LAMPS	PASS 638341
108	ITS 004	SYLVANIA	2005 VALUCRAFT HALOGEN HB5 LAMPS	PASS 638342
108	ITS 005	PILOT	2005 PILOT HALOGEN HB5 LAMPS	PASS 638343
108	ITS 006	AMERICAN PRODUCTS	2005 AMERICAN PRODUCT HALOGEN HB5 LAMPS	PASS 638344
108	ITS 007	AMERICAN AUTO	2000 AMERICAN AUTO A HALOGEN HB5 LAMPS	PASS 638346
108	ITS 008	PILOT	2005 PILOT HALOGEN HB4 LAMPS	PASS 638347
108	ITS 009	PIAA	2005 PIAA HALOGEN HB4 LAMPS	PASS 638348
108	ITS 010	PILOT	2005 PILOT HALOGEN HB2 LAMPS	PASS 638349
108	ITS 011	PIAA	2005 PIAA HALOGEN HB2 LAMPS	PASS 638350
108	ITS 012	AMERICAN AUTO	2000 AMERICAN AUTO A HALOGEN HB3 LAMPS	PASS 638351
108	ITS 013	AMERICAN AUTO	2000 AMERICAN AUTO A HALOGEN HB2 LAMPS	PASS 638352

¹ Under review, Low beam photometry failure.

REPORTS ACCEPTED DURING JUNE 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HS NO.
118	KAR 002	HONDA	2006 HONDA CR-V MPV 4-DOOR	PASS 638334
202	GTL 001	NISSAN	2005 NISSAN ALTIMA 4-DOOR SEDAN	PASS 638366
202	GTL 002	GMC	2005 CHEVROLET EQUINOX MPV 4-DOOR	PASS 638367
202	GTL 003	KIA	2005 KIA RIO 4-DOOR SEDAN	PASS 638368
202	GTL 004	DAIMLER/ CHRYSLER	2005 DODGE GRAND CARAVAN MINIVAN 4-DOOR	PASS 638369
202	GTL 005	TOYOTA	2005 SCION TC 2-DOOR H/BACK	PASS 638370
206	KAR 010	MERCEDES-BENZ	2006 MERCEDES-BENZ ML350 DOOR LATCH/HINGE	PASS 638387
206	KAR 011	MERCEDES-BENZ	2006 MERCEDES-BENZ ML350 DOOR LATCH/HINGE	PASS 638386
206	MGA 016	NISSAN	2006 NISSAN XTERRA DOOR LATCH/HINGE	PASS 638355
206	MGA 017	NISSAN	2006 NISSAN XTERRA DOOR LATCH/HINGE	PASS 638356
206	MGA 018	NISSAN	2006 NISSAN ARMADA DOOR LATCH/HINGE	PASS 638357
209	DTB 007	HYUNDAI	2006 HYUNDAI ELANTRA SEATBELT ASSY.	PASS 638353
209	DTB 008	HYUNDAI	2006 HYUNDAI SONATA SEATBELT ASSY.	PASS 638354
209	UST 013	HONDA	2006 HONDA PILOT DRIVER SEATBELT ASSY.	PASS 638365
209	UST 014	NISSAN	2006 NISSAN ALTIMA DRIVER SEATBELT ASSY.	PASS 638364
209	UST 016	NISSAN	2006 NISSAN MURANO FRONT RH SEATBELT ASSY.	PASS 638362
213	UST 009	COMBI	2006 COMBI CONNECTION CHILD RESTRAINT	PASS 638331
213	UST 026	EVENFLO	2006 EVENFLO EMBRACE CHILD RESTRAINT	PASS 638315
213	UST 028	EVENFLO	2006 EVENFLO TITAN 5 CHILD RESTRAINT	PASS 638316
213	UST 029	EVENFLO	2006 EVENFLO TRIUMPH CHILD RESTRAINT	PASS 638317
213	UST 030	EVENFLO	2006 EVENFLO TRIBUTE CHILD RESTRAINT	PASS 638318
213	UST 031	EVENFLO	2006 EVENFLO TRIBUTE 5 CHILD RESTRAINT	PASS 638319
213	UST 033	EVENFLO	2006 EVENFLO EXPRESS CHILD RESTRAINT	PASS 638326

REPORTS ACCEPTED DURING JUNE 2006 FOR FY 2006 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HS NO.
213	UST 034	EVENFLO	2006 EVENFLO CHASE COMFORT T CHILD RESTRAINT	PASS 638336
213	UST 035	EVENFLO	2006 EVENFLO VISION CHILD RESTRAINT	PASS 638327
213	UST 037	EVENFLO	2006 EVENFLO GENERATIONS CHILD RESTRAINT	PASS 638328
213	UST 046	TRIPLE PLAY	2006 TRIPLE PLAY PRO SIT 'N' STROLL CHILD RESTRAINT	PASS 638332
213	UST 048	BABY TREND	2006 BABY TREND FLEX-LOC CHILD RESTRAINT	PASS 638333
213	UST 051	EVENFLO	2006 EVENFLO DISCOVERY CHILD RESTRAINT	PASS 638330
214	TRC 001	GMC	2006 CHEVROLET HHR 4-DOOR SEDAN	PASS 638335
218	SRI 001	SHANGHAI TUNG	2006 AFX FX-97 COMP. FACIAL MOTORCYCLE HELMET	PASS 638286
218	SRI 002	ARAI HELMET	2006 ARAI PROFILE COMP. MOTORCYCLE HELMET	FAIL-P ² 638358
218	SRI 003	HJC	2006 HJC SYMAX FULL MOTORCYCLE HELMET	PASS 638363
218	SRI 013	DIT	2006 VIVA VIVA 325 PARTIAL MOTORCYCLE HELMET	FAIL-P,L ³ 638388
218	SRI 004	DOING	2006 HOT LEATHER NH30X/DY0401 PARTIAL MOTORCYCLE HELMET	FAIL-P,L ⁴ 638389

²Under review, Impact dwell 200g low temperature.

³Under review, Peak g, penetration, retention and label failure.

⁴Under review, Peak g, penetration, retention and label failure.

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH JUNE 2006
(CI NUMBER SYSTEM EXAMPLE: "CI-208-041220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2004)**

NONE

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH JUNE 2006
(PE NUMBER SYSTEM EXAMPLE: "PE-208-041220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2004)**

PE NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-201-050325	General Motors Corp./2005 Buick Lactosse/Upper roof rail target (Ur2):1164 HIC<1000 HIC	CT
PE-208-050721	Volvo North America Corp./2005 Volvo S40/Data request/Passenger failed Nij	CT

PEs OPENED SINCE LAST REPORT

NONE

PEs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect