

| FEDERAL MOTOR VEHICLE SAFETY STANDARDS | | | | |
|--|-----|--|------------|---------|
| No. | STD | FMVSS TITLE | TYPE | MODE |
| 1 | 101 | Controls and Displays (Inspection) | Vehicle | Insp.-1 |
| 2 | 102 | Transmission Shift Lever Sequence, etc. (I) | Vehicle | Insp.-2 |
| 3 | 103 | Windshield Defrosting & Defogging Systems | Vehicle-1 | TEST |
| 4 | 104 | Windshield Wiping & Washing Systems | Vehicle-2 | TEST |
| 5 | 105 | Hydraulic Brake System | Vehicle-3 | TEST |
| 6 | 106 | Brake Hoses | Equip.-1 | TEST |
| 7 | 108 | Lamps, Reflective Devices, etc. | Equip.-2 | TEST |
| 8 | 109 | Passenger Car New Pneumatic Tires | Equip.-3 | TEST |
| 9 | 110 | Tire Selection & Rims GVWR-64536KG | Vehicle-4 | TEST |
| 10 | 111 | Rearview Mirrors | Vehicle-5 | TEST |
| 11 | 113 | Hood Latch Systems (Inspection) | Vehicle | Insp.-3 |
| 12 | 114 | Theft Protection | Vehicle-6 | TEST |
| 13 | 116 | Hydraulic Brake Fluids | Equip.-4 | TEST |
| 14 | 117 | Retreaded Pneumatic Tires (Inspection) | Equipment | Insp.-4 |
| 15 | 118 | Power Operated Windows, Roofs & Partitions Systems | Vehicle-7 | TEST |
| 16 | 119 | Truck/Bus New Pneumatic Tires | Equip.-5 | TEST |
| 17 | 120 | Tire Selection & Rims GVWR > 4536kg & MC | Vehicle-8 | TEST |
| 18 | 121 | Air Brake Systems | Vehicle-9 | TEST |
| 19 | 122 | Motorcycle Brake Systems | Vehicle-10 | TEST |
| 20 | 123 | Motorcycle Controls & Displays (Inspection) | Vehicle | Insp.-5 |
| 21 | 124 | Accelerator Control Systems | Vehicle-11 | TEST |
| 22 | 125 | Warning Devices | Equip.-6 | TEST |
| 23 | 129 | Passenger Car New Non-Pneumatic Tires | Equip.-7 | TEST |
| 24 | 131 | School Bus Pedestrian Safety Devices | Vehicle-12 | TEST |
| 25 | 135 | Passenger Car Brake Systems | Vehicle-13 | TEST |
| 26 | 138 | Tire Pressure Monitory Systems | Vehicle-19 | TEST |
| 27 | 139 | New Pneumatic tires for light vehicles | Equip.-9 | TEST |
| 28 | 201 | Occupant Protection in Interior Impact | Vehicle-14 | TEST |
| 29 | 202 | Head Restraints | Vehicle-15 | TEST |
| 30 | 203 | Impact Prot. for Driver from Strg. Control | Vehicle-16 | TEST |
| 31 | 204 | Steering Control Rearward Displacement | Vehicle-17 | TEST |
| 32 | 205 | Glazing Materials (Inspection) | Equipment | Insp.-6 |
| 33 | 206 | Door Locks & Door Retention Components | Equip.-8 | TEST |
| 34 | 207 | Seating Systems | Vehicle-18 | TEST |
| 35 | 208 | Occupant Crash Protection | Vehicle-20 | TEST |
| 36 | 209 | Seat Belt Assemblies | Equip.-10 | TEST |

| | | | | |
|--|-----|---|------------|---------|
| 37 | 210 | Seat Belt Assembly Anchorages | Vehicle-21 | TEST |
| 38 | 212 | Windshield Mounting | Vehicle-22 | TEST |
| 39 | 213 | Child Restraint Systems | Equip.-11 | TEST |
| 40 | 214 | Side Impact Protection | Vehicle-23 | TEST |
| 41 | 216 | Roof Crush Resistance | Vehicle-24 | TEST |
| 42 | 217 | Bus Window Retention & Release | Vehicle-25 | TEST |
| 43 | 218 | Motorcycle Helmets | Equip.-12 | TEST |
| 44 | 219 | Windshield Zone Intrusion | Vehicle-26 | TEST |
| 45 | 220 | School Bus Rollover Protection | Vehicle-27 | TEST |
| 46 | 221 | School Bus Body Joint Strength | Vehicle-28 | TEST |
| 47 | 222 | School Bus Passenger Seating | Vehicle-29 | TEST |
| 48 | 223 | Rear Impact Guards | Equip.-13 | TEST |
| 49 | 224 | Rear Impact Protection (Inspection) | Vehicle | Insp.-7 |
| 50 | 225 | Child Restraint Anchorage Systems | Vehicle-30 | TEST |
| 51 | 301 | Fuel System Integrity | Vehicle-31 | TEST |
| 52 | 302 | Flammability of Interior Materials | Equip.-14 | TEST |
| 53 | 303 | Fuel System Integrity of CNG Vehicles | Vehicle-32 | TEST |
| 54 | 304 | CNG Fuel Container Integrity | Equip.-15 | TEST |
| 55 | 305 | Electric Vehicles | Vehicle-33 | TEST |
| 56 | 401 | Interior truck Release | Vehicle-34 | TEST |
| 57 | 403 | Platform Lift Systems for Motor Vehicles | Equip.-16 | TEST |
| 58 | 404 | Platform Lift Installations In Motor Vehicles | Vehicle-35 | TEST |
| 59 | 500 | Low Speed Vehicle Requirements | Vehicle-36 | TEST |
| SUMMARY: 36 vehicle standards, 16 equipment standards, 7 inspection standards | | | | |

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: NOVEMBER 15, 2008

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "CI-208-020320")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "PE-214-020320")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

| | | |
|-----------------|---------------------------|--------------------------|
| IN (Inspection) | CP (Complaint) | MD (Manufacturer Defect) |
| ID (Part 574) | MI (Manufacturer Inquiry) | |

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure

FAIL - I: inspection failure

FAIL - L: labeling or instruction failure

REPORTS ACCEPTED DURING OCTOBER FY 2008 TEST PROGRAM 2008

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

| STD | LAB/GRP | MFR/DISTRIB | MY/MAKE/MODEL/STYLE | RESULT/HSNO |
|-----|---------|---------------|--|-------------------------------|
| 105 | TRC 003 | CHRYSLER LLC | 2008 DODGE SPRINTER VAN | PASS 640140 |
| 105 | TRC 004 | FORD | 2008 ACE TRUCK BODY PICKUP TRUCK 2-DOOR | PASS 640194 |
| 118 | GTL 006 | VOLVO | 2008 VOLVO XC 90 MPV 4-DOOR | PASS 640110 |
| 118 | GTL 007 | HONDA | 2008 HONDA ACCORD 4-DOOR SEDAN | PASS 640111 |
| 118 | GTL 008 | TOYOTA | 2008 TOYOTA SCION XD 4-DOOR H/BACK | PASS 640112 |
| 118 | GTL 009 | MINITUBISHI | 2008 MITSUBISHI LANCER 4-DOOR SEDAN | PASS 640113 |
| 118 | GTL 010 | SUBARU | 2008 SUBARU IMPREZA 4-DOOR SEDAN | PASS 640114 |
| 135 | TRC 010 | GMC | 2008 CHEVROLET TAHOE MPV 4-DOOR | PASS 640139 |
| 201 | CAL 001 | GMC | 2007 CHEVROLET HHR MPV 4-DOOR | FAIL-P ¹ 640185 |
| 201 | MGA 004 | FORD | 2008 FORD FOCUS 4-DOOR SEDAN | PASS 640115 |
| 207 | KAR 002 | TOYOTA | 2009 TOYOTA COROLLA 4-DOOR SEDAN | PASS 640196 |
| 207 | KAR 003 | CHRYSLER LLC | 2008 JEEP LIBERTY MPV 4-DOOR | PASS 640197 |
| 207 | KAR 007 | CHRYSLER LLC | 2008 CHRYSLER 300 4-DOOR SEDAN | PASS 640195 |
| 209 | DTB 004 | HONDA | 2008 HONDA CR-V REAR LH SEAT BELT ASSY. | PASS 640060 |
| 209 | DTB 005 | HONDA | 2008 HONDA RIDGELINE FRONT RH SEAT BELT ASSY. | PASS 640061 |
| 209 | DTB 006 | HONDA | 2008 HONDA FIT DRIVER SEAT BELT ASSY. | PASS 640062 |
| 209 | DTB 007 | HONDA | 2008 ACURA MDX DRIVER SEAT BELT ASSY. | PASS 640150 |
| 209 | DTB 008 | HYUNDAI KIA | 2008 HYUNDAI AZERA DRIVER SEAT BELT ASSY. | PASS 640151 |
| 209 | DTB 009 | HYUNDAI KIA | 2008 HYUNDAI TUCSON REAR RH SEAT BELT ASSY. | PASS 640152 |
| 209 | DTB 010 | HYUNDAI KIA | 2008 KIA OPTIMA DRIVER SEAT BELT ASSY. | PASS 640153 |
| 209 | DTB 011 | HYUNDAI KIA | 2008 KIA SPORTAGE REAR RH SEAT BELT ASSY. | PASS 640154 |
| 209 | DTB 012 | MERCEDES-BENZ | 2008 MERCEDES-BENZ C300 DRIVER SEAT BELT ASSY. | PASS 640155 |

¹ A pillar HIC > 1000. Closed by NHTSA

REPORTS ACCEPTED DURING OCTOBER FY 2008 TEST PROGRAM 2008

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

| STD | LAB/ GRP | MFR/ DISTRIB | MY/MAKE/ MODEL/STYLE | RESULT/ HSNO |
|------------|---------------------|-------------------------|--|--------------------------------|
| 209 | DTB 016 | NISSAN | 2008 NISSAN VERSA FRONT RH SEAT BELT ASSY. | PASS 640156 |
| 209 | DTB 017 | VOLKSWAGEN | 2008 VOLKSWAGON RABBIT DRIVER SEAT BELT ASSY. | PASS 640157 |
| 209 | DTB 018 | VOLKSWAGEN | 2008 AUDI A4 DRIVER SEAT BELT ASSY. | PASS 640158 |
| 209 | DTB 019 | VOLVO | 2008 VOLVO S40 REAR RH SEAT BELT ASSY. | PASS 640159 |
| 209 | DTB 020 | VOLVO | 2008 VOLVO S80 DRIVER SEAT BELT ASSY. | PASS 640160 |
| 213 | MGA 003 | COMBI | 2008 COMBI SHUTTLE INFANT CHILD RESTRAINT | PASS 640141 |
| 213 | MGA 005 | EVENFLO | 2008 EVENFLO DISCOVERY CHILD RESTRAINT | FAIL-L ² 640142 |
| 213 | MGA 007 | EVENFLO | 2008 EVENFLO TITAN ELITE CHILD RESTRAINT | PASS 640143 |
| 213 | MGA 008 | EVENFLO | 2008 EVENFLO TRIUMPH ADVANCE CHILD RESTRAINT | FAIL-L ³ 640144 |
| 213 | MGA 010 | EVENFLO | 2008 EVENFLO TRIBUTE 5 CHILD RESTRAINT | FAIL-L ⁴ 640145 |
| 213 | MGA 013 | EVENFLO | 2008 EVENFLO GENERATIONS CHILD RESTRAINT | PASS 640146 |
| 213 | MGA 014 | EVENFLO | 2008 EVENFLO BOLERO CHILD RESTRAINT | PASS 640147 |
| 213 | MGA 019 | GRACO | 2008 GRACO SNUG RIDE CHILD RESTRAINT | PASS 640148 |
| 213 | MGA 026 | GRACO | 2008 GRACO PLATINUM CARGO CHILD RESTRAINT | PASS 640149 |
| 213 | MGA 028 | GRACO | 2008 GRACO SAFE SEAT TURBO CHILD RESTRAINT | FAIL-L, ⁵ 640084 |
| 213 | MGA 029 | PEG-PEREGO | 2008 PEG-PEREGO PRIMO VIAGGIO SIP CHILD RESTRAINT | PASS 640085 |
| 213 | MGA 030 | RECARO | 2008 RECARO YOUNG SPORT CHILD RESTRAINT | PASS 640104 |
| 213 | MGA 031 | RECARO | 2008 RECARO COMO CHILD RESTRAINT | PASS 640105 |
| 213 | MGA 033 | RECARO | 2008 RECARO START CHILD RESTRAINT | PASS 640106 |
| 213 | MGA 038 | SUNSHINE KIDS | 2008 SUNSHINE KIDS RADIAN 80 CHILD RESTRAINT | FAIL-L ⁶ 640107 |

² Labeling failure, under review

³ Labeling failure, under review

⁴ Labeling failure, under review

⁵ Labeling failure. Petition for Inconsequential Noncompliance which addressed labeling failure granted. Closed by NHTSA.

⁶ Labeling failure, under review

REPORTS ACCEPTED DURING OCTOBER FY 2008 TEST PROGRAM 2008

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

| STD | LAB/GRP | MFR/DISTRIB | MY/MAKE/MODEL/STYLE | RESULT/HSNO |
|------------|----------------|--------------------|--|----------------------------------|
| 213 | MGA 039 | SUNSHINE KIDS | 2008 SUNSHINE KIDS MONTEREY CHILD RESTRAINT | FAIL-L ⁷ 640108 |
| 218 | SRI 005 | AGV | 2008 AGV THUNDER HALF MOTORCYCLE HELMET | FAIL-P ⁸ 640187 |
| 218 | SRI 006 | ARAI | 2008 ARAI XD-3 MOTORCYCLE HELMET | PASS 640188 |
| 218 | SRI 008 | FULMER HELMETS | 2008 FULMER SS MOTORCYCLE HELMET | FAIL-P,L ⁹ 640189 |
| 218 | SRI 010 | QUEEN KWAN | 2008 AFX FX-28 MOTORCYCLE HELMET | FAIL-P ¹⁰ 640190 |
| 218 | SRI 013 | STRATEGIC SPORT | 2008 CRAFT HELMETS RX-1 MOTORCYCLE HELMET | FAIL-L ¹¹ 640193 |
| 218 | SRI 016 | NOLAN HELMETS | 2008 NOLAN N30 FLASHBACK MOTORCYCLE HELMET | PASS 640191 |
| 218 | SRI 017 | ADVANCED CARBON | 2008 ACC EXT-003 MOTORCYCLE HELMET | FAIL-P ¹² 640109 |
| 218 | SRI 019 | HD POWER SPORTS | 2008 VEGA XT HALF MOTORCYCLE HELMET | FAIL-P,L ¹³ 640192 |
| 218 | UST 003 | JIXIANG | 2008 JIXIANG 500 MOTORCYCLE HELMET | PASS 640058 |
| 218 | UST 010 | JIXIANG | 2008 JIXIANG 500 MOTORCYCLE HELMET | PASS 640059 |
| 218 | UST 011 | KIDO SPORTS | 2008 SCORPION EXO-200 MOTORCYCLE HELMET | PASS 640064 |
| 218 | UST 012 | ARAI HELMET | 2008 ARAI RX-7 CORSAIR MOTORCYCLE HELMET | PASS 640065 |
| 218 | UST 013 | NOLAN HELMETS | 2008 NOLAN X-602 MOTORCYCLE HELMET | PASS 640063 |
| 301 | CAL 006 | SUZUKI | 2008 SUZUKI SX4 4-DOOR SEDAN | PASS 640162 |
| 301 | CAL 007 | HONDA | 2008 ACURA RDX MPV 4-DOOR | PASS 640161 |
| 301 | MGA 004 | GMC | 2008 SATURN VUE MPV 4-DOOR | PASS 640135 |
| 301 | MGA 005 | FORD | 2008 FORD ESCAPE MPV 4-DOOR | PASS 640137 |
| 305 | MGA 004 | GMC | 2008 SATURN VUE MPV 4-DOOR | PASS 640136 |

⁷ Labeling and inspection failures, under review

⁸ Impact attenuation dwell time failures, under review

⁹ Labeling and impact attenuation dwell time failures, under review

¹⁰ Penetration failures, under review

¹¹ Labeling failure, under review

¹² Penetration and impact attenuation dwell time failures, under review

¹³ Labeling and impact attenuation dwell time failures, under review

REPORTS ACCEPTED DURING OCTOBER FY 2008 TEST PROGRAM 2009

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

| STD | LAB/ GRP | MFR/ DISTRIB | MY/MAKE/ MODEL/STYLE | RESULT/ HSNO |
|------------|---------------------|-------------------------|---------------------------------|-------------------------|
| 131 | TRC 001 | THOMAS | 2009 THOMAS MINOTOUR BUS | PASS 640208 |
| 305 | MGA 005 | FORD | 2008 FORD ESCAPE MPV 4-DOOR | PASS 640138 |

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L – LABELING

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH OCTOBER 2008
(CI NUMBER SYSTEM EXAMPLE: "CI-208-071220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2007)**

NONE

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH OCTOBER 2008
(PE NUMBER SYSTEM EXAMPLE: "PE-208-071220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2007)**

| PE NO. | MFR/MY/MAKE/MODEL/FAILURE | CAUSE |
|----------------|--|--------------|
| PE-108-080515 | Matrix Racing/Reflex reflector physical inspection | MI |
| PE-108-080716 | Volkswagen of North America/2008 Volkswagen Golf/Physical inspection | MI |
| PE-108-080912B | Sabersport/Reflex reflector physical inspection | MI |
| PE-108-080912A | Dope, Inc./Reflex reflector physical inspection | MI |
| PE-108-080516 | Boken Corporation/Boken/Physical inspection | MI |
| PE-108-080516 | Allsman Enterprises/Allsman/Physical inspection | MI |
| PE-108-080516 | Sportiva Motors/Sportiva/Physical inspection | MI |

PEs OPENED SINCE LAST REPORT

NONE

PEs CLOSED SINCE LAST REPORT

| PE NO. | MFR/MY/MAKE/MODEL/FAILURE |
|----------------|--|
| PE-108-080516C | Got Hids/2008 Hid Cool/Physical inspection/Closed by NHTSA 8/6/2008 |
| PE-108-080516E | Fortex International/2008 Eagle/Physical inspection/Closed by NHTSA 8/6/2008 |
| PE-108-080604 | Best Dubs Corp./2008 Hid conversion/Physical inspection/Closed by NHTSA 8/7/2008 |
| PE-108-080225 | Genera Corp./2008 Tyc/Dodge/Halogen Headlamps Photometric Test/Closed by NHTSA 8/04/2008 |

CAUSE:

PE Petition
 CT Compliance Test
 IN Inspection
 CP Complaint
 ID Part 574
 MI Mfgr. Inquiry
 MD Mfgr. Defect